



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2016-32R4	2020-10-16	BOMBARDIER	CL-600 (Challenger)	Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge / Canister Fuel Leakage
2020-0225	2020-10-16	AIRBUS	A380	Nacelles / Pylons - Pylon Box Zone D Sealing - Modification
2020-0224-E	2020-10-16	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Tail Rotor - Tail Rotor Blades - Inspection / Replacement / Modification
2020-18-16	2020-10-16	BOEING	767	NOT ADOPTED - EASA DECISION ATTACHED
2020-0226-E	2020-10-16	HOFFMANN PROPELLER GmbH & Co. KG	HO-V 72	Propellers - Propeller Hub - Inspection / Replacement
CF-2020-39	2020-10-15	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Nacelles/Pylons - Main Landing Gear Side Brace Fitting to A-frame Joint - Fastener Holes Not Cold-worked
2019-0197R1	2020-10-14	AIRBUS	A318, A319, A320	Fuel - Fuel Level Sensor Support Bracket - Replacement
2020-0222	2020-10-14	AIRBUS	A321	Fuselage - Door Frame Drill Starts - Inspection
US-2020-21-13	2020-10-14	GENERAL ELECTRIC	GE90	Engine - High-Pressure Turbine Rotor Stage 2 Disks and Rotating Compressor Discharge Pressure Seals - Replacement
US-2020-19-08	2020-10-14	BELL TEXTRON INC. (BTI)	204B, 205, 212	Main Rotor - Main Rotor Hub Tension-torsion Strap Assembly - Life Limit / Removal
2020-0223	2020-10-14	SAAB AB	2000	Landing Gear - Transfer Valve Installation - Modification
2020-0220	2020-10-13	AIRBUS	A350	Wings - Upper / Lower Wing Skin Cover Edge Glow Sealant - Inspection
2020-0221	2020-10-13	ATR	ATR42	Instruments - Angle of Attack Probe Electrical Routing - Inspection
2020-0219	2020-10-12	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment
2020-0218	2020-10-12	AIRBUS	A319	Fuselage - Cabin Swift Broadband Antenna Doubler - Inspection / Replacement
CF-2020-36	2020-10-09	AIRBUS CANADA LP	BD-500 (A220 Series)	Flight Controls - Software Update
US-2020-20-13	2020-10-09	GENERAL ELECTRIC	CF6-80A, CF6-80C	Engine - High-Pressure Turbine Stage 1 and Stage 2 Disks - Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2020-35	2020-10-09	BOMBARDIER	BD-700	Flight Controls - Roll Control Input-Modules (RCIMs) Incorrect Installation
US-2020-20-04	2020-10-08	ROLLS-ROYCE CORPORATION (USA)	AE 2100	Engine - Maintenance Manual Airworthiness Limitations Section - Revision
US-2020-20-10	2020-10-08	AVIATION PARTNERS BOEING, BOEING, VT MOBILE AEROSPACE ENGINEERING	EASA STC 10015659, FAA STC ST01518SE, STC EASA.IM.A.S.01636, 757, FAA STC ST03952AT	Fuselage - Fuselage Frame - Inspections / Repair
US-2020-20-17	2020-10-08	GENERAL ELECTRIC	GE90	Engine Controls - Engine Indicating and Crew Alerting System - Dispatch Prohibition
CF-2020-34	2020-10-07	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Flight Controls - Rudder Actuator Bracket - Cracked or Missing Nuts
CF-2020-33	2020-10-07	BOMBARDIER	BD-100	Navigation - Flight Management System - Wrong Magnetic Heading Displayed due to Outdated Magnetic Variation Tables
2020-0214	2020-10-06	DASSAULT AVIATION	Falcon 7X	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2020-0217-E	2020-10-06	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Equipment / Furnishings - Cyclic Stick Grip UP/DOWN Hoist Control Switch - Operational Limitation / Rotorcraft Flight Manual - Amendment
2020-0215	2020-10-06	DASSAULT AVIATION	Falcon 10	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
CF-2015-01R2	2020-10-05	PRATT & WHITNEY CANADA	PT6B	Engine Indicating - Incorrect Engine Torque Indication
2020-0208	2020-10-05	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine - Intermediate Pressure Compressor Rotor Shaft - Inspection
2020-0209	2020-10-05	AIRBUS	A330	Fuselage - Wing-to-Fuselage Fillet Fairing Adjustable Rods - Replacement
2020-0212	2020-10-05	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Rotor Drive(s) - Tail Rotor Drive Flange - Inspection / Modification
2020-0210	2020-10-05	AIRBUS	A350	Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
2008-0072-CN	2020-10-05	DASSAULT AVIATION	Falcon 10, Falcon 2000, Falcon 900EX, Fan Jet Falcon, Mystère-Falcon 20, Mystère-Falcon 20GF/200, Mystère-Falcon 50, Mystère-Falcon 900	CANCELLED: Air Conditioning - Pressurization Control Regulating Valve - Check
2020-0211	2020-10-05	AIRBUS	A350	Time Limits / Maintenance Checks - System Equipment Maintenance Requirements - ALS Part 4 - Amendment