



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-22-02	2020-10-30	GENERAL ELECTRIC	CF6-80C, CF6-80E1	Engine Fuel and Control - Hydromechanical Unit - Removal / Replacement
2015-0218R1	2020-10-28	AIRBUS	A318, A319, A320, A321	Fuselage - Cabin / Cargo Compartment Parts - Inspection / Replacement [Wrong Material]
2020-0237	2020-10-28	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Lights - Emergency Light Power Units - Replacement
2020-0236	2020-10-27	AIRBUS	A318, A319, A320, A321	Equipment / Furnishings - Emergency Escape Slide / Raft Inflation Reservoir - Pressure Check
2020-0234	2020-10-27	AIRBUS	A330	Fuselage - Forward Lower Deck Cargo Compartment / Fire Extinguishing Bottle Support Brackets and Strut Assembly - Modification / Replacement
2020-0235	2020-10-27	SONACA AIRCRAFT S.A.	S2	Equipment / Furnishings - Seat Belt Restraint System - Inspection / Modification
CF-2020-44	2020-10-27	BOMBARDIER	CL-600 (Challenger)	Fuselage - Fuselage Station 559 Circumferential Joint - Interface Metal Chips from Improper Hole Deburring
2020-0233	2020-10-27	SCHEMPP HIRTH FLUGZEUGBAU	Duo Discus Sailplanes, Duo Discus T	Flight Controls - Airbrake End Stops / Bushings - Inspection / Replacement
2020-0232	2020-10-26	AIRBUS	A380	Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - Airworthiness Limitations Section Part 2 - Amendment
US-2020-18-02	2020-10-26	BOEING	747	NOT ADOPTED - EASA DECISION ATTACHED
CF-2019-31R1	2020-10-23	AIRBUS CANADA LP	BD-500 (A220 Series)	Ice and Rain Protection - Insufficient Engine Core Ventilation Resulting in Higher Engine Core Temperatures
CF-2020-43	2020-10-22	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Landing Gear - Main Landing Gear Drag Strut - Longitudinal Cracking
2020-0230	2020-10-22	LEONARDO S.p.A. HELICOPTERS	A109/A119	Rotor - Main Rotor Blade Tip Cap - Inspection
CF-2020-37	2020-10-22	BOMBARDIER	BD-700	Fuel - Refuel Defuel Tube - Mislocated Bracket Assembly



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-18-09	2020-10-20	HONEYWELL INTERNATIONAL INC.	ALF502, LF507	Engine Fuel and Control - Overspeed Fuel Solenoid Valve Assembly & Fuel Filter Outlet - Inspection
2020-0228	2020-10-20	CONTINENTAL AEROSPACE TECHNOLOGIES, GmbH	EASA STC 10014287, EASA STC 10014364, TAE125	Engine - Turbocharger Hose - Replacement
CF-2020-42	2020-10-20	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Application of Additional Protection on Waste Box to Inhibit Future Corrosion Development
CF-2020-41	2020-10-20	AIRBUS CANADA LP	BD-500 (A220 Series)	Engine - Aircraft Flight Manual - Operating Limitations
US-2020-20-09	2020-10-20	BOEING	787	Flight Controls - Flight Control Electronics Common Block Point 5 Software - Installation
2020-0229	2020-10-20	PILATUS AIRCRAFT LTD	PC-12	Fuel - Fuel Transfer Ejector - Replacement
CF-2020-38	2020-10-20	BOMBARDIER	CL-600 (Challenger)	Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge / Canister Fuel Leakage
2020-0227	2020-10-19	ATR	ATR72	Electrical Routing - Electrical Harness Routes 1M and 1S-1V - Modification
CF-2020-40	2020-10-19	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fuselage - Understrength Floor Attachment Structure beneath Galley 2 at Fuselage Station 389.90