



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------------|------------|-------------------------------------|---------------------------|---|
| 2021-0044 | 2021-02-05 | LEONARDO S.p.A. HELICOPTERS | AB139/AW139 | Electrical Power - Overhead Panel - Inspection |
| 2021-0039R1 | 2021-02-03 | BOEING | 737 | Return to Service |
| 2021-0043-E | 2021-02-02 | CEAPR | DR 400 | Air Conditioning - Cabin Heater and Carburettor Heater Ducts - Operational Restriction / Inspection |
| US-2020-26-14 | 2021-02-02 | MITSUBISHI HEAVY INDUSTRIES LTD. | MU-2B (USA production) | Propeller Pitch Control Lever / Linkage - Inspection / Modification |
| ISR-I-57-2020-06-01 | 2021-02-01 | GULFSTREAM (GALP) | G280 | Instructions to install a doubler at the attachment location of the wing Rib 0 and the front spar. |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|--------------|------------|--|---|---|
| 2021-0042 | 2021-01-29 | AEROSTATS, BALLONS CHAIZE, BALLONS LIBERT, BALLONSERVICE & TECHNIK, BALONY KUBICEK, CAMERON BALLOONS, LINDSTRAND TECHNOLOGIES, NOTHEISZ BALLOONS HUNGARY Kft., SCHROEDER FIRE BALLOONS, SUP-AIR BALLON EGYESULET, ULTRAMAGIC | MA Series Hot Air Balloons, CS SERIES HOT AIR BALLOONS, JZ SERIES HOT AIR BALLOONS, JZX SERIES HOT AIR BALLOONS, Libert Hot Air Balloons, Schoen Hot Air Balloons, AB 2 Hot Air Balloons, AB 8 Hot Air Balloons, AEROTECHNIK AB Hot Air Balloons, BB Hot Air Balloons, Special Shape Hot Air Balloons, A Type, A Type Cloudhopper, B Type, C Type, Cameron Special Shape Hot Air Balloons, Gas Balloons, Helium-Hot Air Balloons, Hot Air Balloons, L Type, Lindstrand Special Shape Hot Air Balloons, S Type, Sky Hot Air Balloons, X Type, 203T HiFlyer, Series 1, Series 2, Series R, Series Special Shapes, TGB, TOMI Series, fire balloons G, fire balloons S - Special Shape Balloons, SUP- AIR Series, Hot Air Balloons, Special Shape Hot Air Balloons | Hot Air Balloons - Burner Assembly and Hanger - Inspection / Modification |
| 2020-0104R1 | 2021-01-28 | AIRBUS | A318, A319, A320, A321 | Oxygen - Oxygen Supply Solenoid Valve - Inspection / Replacement |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|-----------------------|------------|--------------------------------|--------------------|--|
| ISR-I-04-2020-06-02R1 | 2021-01-28 | GULFSTREAM (GALP) | G280 | Temporary Limitations and Inspection Requirements of the Section 05-10-10 Airworthiness Limitations Section - Airplane Maintenance Manual Revision |
| US-2020-26-13 | 2021-01-28 | SIKORSKY | S-92 | Horizontal Stabilizer - Forward Root Fitting / Strut Fitting - Life Limit / Inspection |
| 2021-0041 | 2021-01-28 | AIRBUS HELICOPTERS | SA/AS 365 / EC 155 | Doors - Placards - Installation / Rotorcraft Flight Manual - Section Emergency Procedures - Amendment |
| 2021-0040 | 2021-01-27 | LEONARDO S.p.A. HELICOPTERS | A109/A119 | Instruments - Wiring - Inspection / Modification |
| 2021-0038 | 2021-01-26 | AIRBUS HELICOPTERS | EC175 | Time Limits / Maintenance Checks - Airworthiness Limitations Section / 04-10 Limitations and 04-20 Inspections - Amendment |
| 2021-0036-E | 2021-01-25 | DASSAULT AVIATION | Falcon 7X | Oxygen - Crew Oxygen Mask Stowage Boxes - Inspection |
| US-2021-01-02 | 2021-01-25 | M7 AEROSPACE LLC | SA26 | Propellers - Pitch Control Lever and Assembly - Inspection / Replacement |
| 2021-0037 | 2021-01-25 | AIRBUS | A340 | Flight Controls - Trimmable Horizontal Stabilizer Actuator - Modification |
| 2021-0033 | 2021-01-25 | AIRBUS | A330, A340 | Flight Controls - Trimmable Horizontal Stabilizer Actuator Lower Attachment Parts - Inspection |
| 2021-0035 | 2021-01-25 | AIRBUS | A330 | Exhaust - Thrust Reverser Translating Cowl Pressure Seals - Inspection / Rework |