



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0084	2021-03-19	IRKUT CORPORATION JSC	RRJ-95	Doors - Entry and Service Doors / Emergency Power Assist System - Operational Check / Inspection / Modification
US-2021-02-14	2021-03-19	BOEING	737	Fuel - Side of Body Slot - Inspection
2021-FATA-01020A-01	2021-03-19	IRKUT CORPORATION JSC	RRJ-95	NOT ADOPTED - EASA DECISION ATTACHED
US-2021-01-04	2021-03-19	BOEING	737	Doors - Upper Aft Corner Stop Fitting Assembly - Inspection / Replacement
2021-0082	2021-03-19	AIRBUS	A380	Nacelles / Pylons - Aft Pylon Fairing Rear Drain Pipes Sealing - Modification
2021-0085	2021-03-19	AIRBUS	A350	Doors - Passenger Door Guide Arms - Replacement / Inspection / Modification
CF-2021-10	2021-03-19	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment / Furnishings - Vibration on Fuselage and Emergency Locator Transmitter (ELT) Antenna
2021-0081	2021-03-18	IRKUT CORPORATION JSC	RRJ-95	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2021-04-12	2021-03-18	ROBINSON HELICOPTER COMPANY	R66	Tail Rotor Drive Shaft Forward Hanger Bearings - Installation / Replacement
2021-0079	2021-03-17	AIRBUS HELICOPTERS	EC 120 B	Tail Rotor - Blades - Inspection
2021-0078	2021-03-17	LEONARDO S.p.A. HELICOPTERS	AW189	Lights - Main Rotor Tip Light Fairings - Replacement
2021-0080	2021-03-17	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	Tay	Engine - Low Pressure Turbine Stage 2/3 Discs - Inspection / Replacement
2021-0075	2021-03-16	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Fuselage - Splice of Frame X5295 - Inspection / Repair / Modification
CF-2021-08	2021-03-16	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Fuel System - Fuel Terminal - High Level Sensor Terminal Screw in Contact with Access Panel
CF-2021-09	2021-03-15	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Twisted Motive Flow Flexible Fuel Line
2021-0073	2021-03-15	AIRBUS	A380	Fuel - Engine Low Pressure Shut Off Valve Electrical Harness Routing - Modification
2021-0063R1	2021-03-15	AIRBUS	A380	Oxygen - Steel Braided Polyurethane Flexible Hoses - Replacement
2021-0074	2021-03-15	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotors Flight Control - Collective Bellcrank - Inspection
2021-0072-E	2021-03-12	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Equipment / Furnishings - Hoist Support - Inspection / Replacement
2021-0071	2021-03-12	AIRBUS	A330	Aircraft Flight Manual - Take-off Distance Determination Procedure - Amendment
2021-0070	2021-03-11	M&D FLUGZEUGBAU	JS-MD Single	Flight Controls - Airbrake Blade No. 3 - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0069	2021-03-11	AIRBUS HELICOPTERS	EC 120 B	Tail Rotor - Hub Body - Inspection / Replacement
2021-0068	2021-03-11	AIRBUS	A340	Flight Controls - Trimmable Horizontal Stabilizer Actuator - Replacement
2021-0055R1	2021-03-10	AUSTRO ENGINE GMBH	E4	Engine - Oil Pump - Replacement
US-2021-05-51	2021-03-10	PRATT & WHITNEY	PW4070, PW4080, PW4090	[Final Rule] Engine - 1st-Stage Low-Pressure Compressor Blades - Inspection
US-2021-06-03	2021-03-09	BOEING	777	Water - Potable Water System - Deactivation
2021-0067	2021-03-09	LEONARDO S.p.A. HELICOPTERS	A109/A119	Main Rotor Drive - Rotor Brake Control Cable - Inspection
2021-0066	2021-03-08	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Equipment / Furnishings - Outboard Load System Fittings - Inspection / Re-identification
2021-0065	2021-03-08	LEONARDO S.p.A. HELICOPTERS	A109/A119	Electrical Power - Wiring Protection - Modification
2015-0197R1	2021-03-08	AIRBUS	A380	Fuselage - Frame 74 to 90 / Shim Sheet on Section 18.1 - Inspection / Repair