



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0234R1	2023-05-11	AIRBUS S.A.S., ATR, BOEING, BOMBARDIER, DE HAVILLAND AIRCRAFT OF CANADA LTD., FOKKER SERVICES, MHI RJ Aviation ULC	A318, A319, A320, A321, A330, A340, ATR42, ATR72, 737, 757, 767, 777, CL-600 (Challenger), DHC-8, CRR-0146, CRR-0185, CRR-0186, CRR-0190, CRR-0206, CRR-0210, CRR-0241, CRR-0265, CRR-0290, CRR-0300, CRR-0309, EASA STC 10046185, EASA STC 10061825, ECR016073, F27, F28, CL-600 (Regional Jet)	Information Systems - Electronic Flight Bag Universal Serial Bus Receptacle - Modification
2023-0099	2023-05-11	DASSAULT AVIATION	Falcon 2000	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2023-0100	2023-05-11	DASSAULT AVIATION	Falcon 2000	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
CF-2023-33	2023-05-11	BOMBARDIER	BD-100	Ice and Rain Protection - Air Data Probes and Sensors - Heater Current Monitor Unit Failure Detection
2023-0098	2023-05-11	AIRBUS S.A.S.	A380	Wings - Front and Rear Spars - Inspection
CF-2023-32	2023-05-10	BOMBARDIER	CL-600 (Challenger)	Landing Gear - Main Landing Gear Shock Strut Lower Pin Cracking
BR-2023-02-02R1	2023-05-10	EMBRAER S.A.	ERJ 190	Main Landing Gear Side Stay Upper Spindle Assembly - Inspection / Replacement
CF-2021-51R1	2023-05-10	VIKING AIR LTD	CL-215	Equipment / Furnishings - Water Bombing System - Un-commanded Water Door Opening
2021-0139R1	2023-05-10	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Cabin Lateral Sliding Plug Door Emergency Jettisoning System - Inspection / Modification
2023-0096-E	2023-05-09	ISSOIRE AVIATION	APM 20, APM 30, APM 40 (Simba)	Wings - Flap Lever Screw - Inspection
CF-2023-30	2023-05-09	PRATT & WHITNEY CANADA	PW307	Engine - High Pressure Turbine 1st / 2nd Stage Disks - Suspected Material Defect
CF-2023-31	2023-05-09	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment / Furnishings - Fixed Emergency Locator Transmitter
CF-2023-29	2023-05-09	BOMBARDIER	BD-100	Nacelles / Pylons - Pylon Aft Engine Mount Attachment Bolts - Discarding and Replacement of Bolts not Performed
US-2023-05-06	2023-05-09	BOEING	737	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2022-03R1	2023-05-09	BOMBARDIER	BD-100	Flight Controls - Horizontal Stabilizer Trim Switch - Unintended Horizontal Stabilizer Motion
US-2023-06-15	2023-05-08	BOEING	737	Fuselage - Left and Right Side Station 727 Frame Inner Chord and S-18A Web - Inspection
US-2023-05-17	2023-05-08	GENERAL ELECTRIC	GE90	Engine - High Pressure Turbine Stage 2 Nozzles and Blades / Exhaust Centerbody - Inspection / Replacement
2023-0094	2023-05-08	AIRBUS S.A.S.	A318, A319, A320, A321, A330, A340	Oxygen - SafeLav Gaseous Oxygen Container - Replacement
2023-0095	2023-05-08	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Fuel - Fuel Filter - Inspection
2023-0093	2023-05-05	AIRBUS S.A.S.	A319, A320, A321	Landing Gear - Braking and Steering Control Unit - Replacement / Master Minimum Equipment List - Amendment Electric and Electronic Common Installation - Relays - Replacement
2023-0092	2023-05-05	AIRBUS S.A.S.	A310	Time Limits / Maintenance Checks - Airworthiness Limitation Section Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment
CF-2023-27	2023-05-05	AIRBUS CANADA LP	BD-500 (A220 Series)	Electrical System Installation - Rear Cabin - Low Clearance Condition
CF-2023-28	2023-05-05	AIRBUS CANADA LP	BD-500 (A220 Series)	Fire Protection - Fire Extinguisher Bottle Available Push Button Annunciators (PBAs) - Do Not Illuminate After Direct Current (DC) Bus Loss
2023-0091	2023-05-05	AIRBUS S.A.S.	A300-600	Time Limits / Maintenance Checks - Airworthiness Limitation Section Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment
2023-0089	2023-05-04	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Stabilizers - Vertical Fin - Inspection Placards and Markings - Interior Placards - Installation Aircraft Flight Manual / Airspeed Limitations - Amendment
2023-0090	2023-05-04	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Rotors Flight Control - Tail Rotor Actuator - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2023-26	2023-05-04	BOMBARDIER	BD-100	Flight Controls - Pitch Trim - Mis-Trimmed Horizontal Stabilizer Leading to Controllability Issues
US-2023-04-11	2023-05-03	GENERAL ELECTRIC	CF6-45, CF6-50	Engine - Low Pressure Turbine Rotor Stage 3 Disks - Inspection / Removal / Replacement