



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2024-24	2024-06-21	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Horizontal Stabilizer (H-Stab) - Anti Yaw Steady Fitting Block - Missing or Loose Bolts
2024-0115-CN	2024-06-21	SAFRAN HELICOPTER ENGINES	ARRIUS 2	CANCELLED: Engine Fuel and Control - Check of Correct Position of Adjusted Fuel Control Unit
2024-0114	2024-06-21	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0116	2024-06-21	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT XWB	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
CF-2024-23	2024-06-20	AIRBUS CANADA LP	BD-500 (A220 Series)	Fire Protection - Fire Extinguisher - Defective Cargo Fire Extinguisher Bottles
US-2024-11-03	2024-06-20	INTERNATIONAL AERO ENGINES AG	V2500-()5	Engine - 1st-Stage Hubs and 2nd-Stage Hubs - Inspection / Replacement
BR-2023-06-01R1	2024-06-20	EMBRAER S.A.	ERJ 190	Wings - Aileron Control System Backlash - Inspection
BR-2023-05-02R1	2024-06-20	EMBRAER S.A.	ERJ 190	Flight Controls - Aileron Control System Backlash - Inspection
US-2024-10-07	2024-06-18	BOEING	757	Fuselage - Fuselage Skin Door Cutout - Inspection / Maintenance Records Check
US-2024-10-05	2024-06-18	BOEING	757	Equipment / Furnishings - Decompression Panels and Pressure Equalization Valves in the Forward and Aft Lower Lobe Cargo Compartments - Inspections / Replacement / Installation
CF-2024-22	2024-06-14	BOMBARDIER	BD-700	Navigation - Required Navigation Performance Authorization Required (RNP-AR) Approach Vertical Deviation
2024-0113	2024-06-13	AIRBUS HELICOPTERS	AS 350 / EC 130	Tail Rotor - Tail Rotor Hub Tension-Torsion Bars - Inspection
2024-0074-CN	2024-06-13	Blackshape S.p.A.	BS 115	CANCELLED: SUSPENSION OF FLIGHT OPERATIONS



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0111	2024-06-12	CONTINENTAL AEROSPACE TECHNOLOGIES, INC., LYCOMING ENGINES	6-285, A-65, C-115, C-125, C145, C75, C85, C90, C90 (RR), E165, E185, GO-300, GTSIO-520, IO-240, IO-346, IO-360, IO-470, IO-520, IOF-240, LIO-470, LIO-520, LTSIO-360, LTSIO-520, O-200, O-200 (RR), O-240, O-300, O-300 (RR), O-470, TSIO-360, TSIO-470, TSIO-520, TSIO-550, TSIOL-550, AEIO-540, AEIO-580, GO-435, GO-480, GSO-480, HO-360, IGSO-480, IGSO-540, IO-360, IO-540, IO-580, IO-720, IVO-540, LO-360, LTIO-540, LTO-360, O-235, O-290, O-320, O-340, O-350, O-360, O-435, O-540, TIGO-541, TIO-360, TIO-540, TIO-541, TO-360, TVO-435, VO-435, VO-540	Reciprocating Engine - Inspection
2023-0048-CN	2024-06-12	CEAPR	DR 400	CANCELLED: Wings - Main Wing Spar Placards and Markings - Interior Placards - Installation Aircraft Flight Manual / Operational Limitations - Amendment
2024-0112-E	2024-06-12	ELIXIR AIRCRAFT	Elixir	Power Plant - Engine Mount - Inspections / Replacement
US-2024-10-15	2024-06-11	GULFSTREAM AEROSPACE CORPORATION	GVII	Powerplant - Engine Mounts - Inspection / Repair / Revision of Aircraft Maintenance Manual