



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2023-02-01R3	2024-10-25	EMBRAER	EMB-505 (Phenom 300)	Flight Controls - Aileron Autopilot Servo Mount Clutch Retaining Bolt - Replacement
2024-0208	2024-10-25	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations Items - Amendment
2024-0125R1	2024-10-24	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor - Rotating Swashplate Yokes - Inspection
2024-0207	2024-10-24	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Engine - Gas Generator First Stage High Pressure Turbine Blades - Replacement
US-2024-21-01	2024-10-24	BOEING	717	Wings - Lower Aft Skins, External Doublers and Rear Spar Lower Caps - Inspections
CF-2024-35	2024-10-23	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Communication - Cockpit Voice Recorder (CVR) - Impact Switch Found Installed in Wrong Direction
CF-2024-36	2024-10-23	AIRBUS CANADA LP	BD-500 (A220 Series)	Flight Controls - Primary Flight Control Computer Software Deficiencies
US-2024-18-02	2024-10-23	BOEING	787	Equipment / Furnishings - Captain's Seat Assembly - Replacement
2024-0195R1	2024-10-22	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Electronic Engine Control Unit - Software Update Preference Injector - Non-extinguishing Test / Replacement
2024-0204	2024-10-22	AIRBUS S.A.S.	A319, A320	Fuselage - Rivet Holes at Frame 64 - Inspection
2024-0203	2024-10-22	AIRBUS S.A.S.	A318, A319, A320, A321	Flight Controls - Trimmable Horizontal Stabilizer Actuator - Replacement
2024-0205	2024-10-22	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor - Rotating Swashplate Yokes - Inspection / Restoration / Service Life Limit
US-2024-16-10	2024-10-22	BOEING	737	Indicating / Recording System - Aeroplane Flight Manual / Display Unit Software Errors - Installation of New Software
2024-0202-E	2024-10-22	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Fuel Control Unit - Replacement
2024-0206-E	2024-10-22	AIRBUS HELICOPTERS	H160	Main Rotor - Rotating Scissors Spherical Bearings - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2024-10-02	2024-10-21	EMBRAER	EMB-545/-550 (Legacy 500)	Landing Gear - Nose and Main Landing Gear Down Lock Spring Assemblies - Inspection
2024-0200	2024-10-21	AIRBUS S.A.S.	A330	Fuselage - Splice Fittings - Inspection
2024-0201	2024-10-21	AIRBUS S.A.S.	A319, A320, A321	Wings - Outer Wing Bottom Buttstrap - Inspections
2024-0196	2024-10-18	AIRBUS S.A.S.	A318, A319, A320, A321	Pneumatic - Overheat Detection System Sensing Elements - Inspection
2024-0197	2024-10-18	AIRBUS S.A.S.	A318, A319, A320, A321, A330, A340	Oxygen - SafeLav Gaseous Oxygen Container - Replacement
2024-0199	2024-10-18	AIRBUS S.A.S.	A319, A320, A321, A330, A350, A380	Cabin Systems - Antenna Adapter Plate - Inspection
2024-0198	2024-10-18	AIRBUS S.A.S.	A300-600, A300-600ST (Beluga), A310, A318, A319, A320, A321, A330, A340	Oxygen - Chemical Oxygen Generators - Replacement
BR-2020-01-02R3	2024-10-17	EMBRAER S.A.	ERJ 170, ERJ 190	[Correction] Nacelles / Pylons - Engine Inboard and Outboard Pylon Lower Link Lugs - Inspection / Repair
ISR-I-32-24-10-01R1	2024-10-16	GULFSTREAM (GALP)	G150	Nose Landing Gear Actuator to Strut Attachment Pin Inspection / Life Limit AMM Revision
BR-2020-04-01R3	2024-10-16	EMBRAER	EMB-545/-550 (Legacy 500)	Windows - Cockpit Side Windows - Inspection / Replacement
CF-2024-34R1	2024-10-16	AIRBUS CANADA LP	BD-500 (A220 Series)	Electrical Power - Variable Frequency Generator Power-Feeder Harness Chafing Against Wheel Bins and Main Landing Gear
US-2024-20-02	2024-10-15	BOEING	717, DC-9	Fuselage - Aft Fuselage Cant Bulkhead at Certain Stations and Vertical Stabilizer Rear Spar Structure - Inspection
2024-0194	2024-10-15	GE AVIATION CZECH	M601	Engine - Centrifugal Compressor Case - Inspections
BR-1999-02-01R7	2024-10-14	EMBRAER S.A.	EMB-145	Aileron PCA Rod Ends and Fittings - Inspections
US-2024-15-09	2024-10-14	TAMARACK AEROSPACE GROUP, Inc., TEXTRON AVIATION INC.	EASA STC 10056170, FAA STC SA03842NY, 525 (CitationJet)	Flight Controls - Tamarack Active Technology Load Alleviation System (ATLAS) Winglets - Placard Installation / AFM Revision
US-2024-16-09	2024-10-14	BOEING	777	Fuselage - Underwing Longeron (UWL) - Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
US-2024-19-14	2024-10-14	BOEING	777	Fuel - Lightning Protection for the Engine Fuel Feed System - Inspections