



Publ. number	Issue Date	TC Holder	Type	Subject
US-2024-18-08	2024-11-08	BOEING	737	Equipment / Furnishings - Galley Wire Bundle Spiral Wrap Sleeving - Identification / Replacement
US-2024-19-06	2024-11-08	BOEING	737	Ice/Rain Protection System - Standby Power System Control Unit - Installation / Power Tests
2021-0280R1	2024-11-08	AIRBUS S.A.S.	A380	Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection
2024-0211-E	2024-11-07	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Main Landing Gear - Main Landing Gear Shock Absorber - Inspection
CF-2024-37	2024-11-05	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Fuel Transfer Valve - Fuel Transfer Float Valve Failed in Closed Position
US-2024-19-15	2024-11-04	APPLIANCES	ATA 35 OXYGEN	SAFRAN AEROSYSTEMS - Oxygen Cylinder and Valve Assemblies - Inspection / Replacement
US-2024-21-02	2024-11-04	LYCOMING ENGINES	AEIO-320, AEIO-360, AEIO-390, AEIO-540, AEIO-580, AIO-320, AIO-360, HIO-360, HIO-390, HIO-540, HO-360, IO-320, IO-360, IO-390, IO-540, IVO-360, IVO-540, LHIO-360, LIO-320, LIO-360, LO-360, LTIO-540, LTO-360, O-233, O-235, O-320, O-340, O-360, O-435, O-540, SO-580, TEO-540, TIGO-541, TIO-360, TIO-540, TIO-541, TIVO-540, TO-360, TVO-435, TVO-540, VO-360, VO-435, VO-540, VSO-580	Reciprocating Engine - Connecting Rod Bushing - Inspections / Replacement
US-2024-19-01	2024-11-04	BOEING	747	Fuselage -Upper Fastener Row of the Fuselage Skin Lap Splice - Inspections
2022-0047-CN	2024-10-31	BELL TEXTRON INC. (BTI)	212, 412	CANCELLED: Fuselage - Tailboom Attachment - Inspection / Replacement
US-2024-16-19	2024-10-31	BELL TEXTRON INC. (BTI)	212, 412	Fuselage - Tailboom Attachment - Inspection / Replacement
US-2024-17-02	2024-10-31	BELL TEXTRON INC. (BTI)	204B, 205, 210	Fuselage - Tailboom Attachment - Inspection / Replacement
US-2024-18-07	2024-10-30	BOEING	737	Equipment / Furnishings - Support Brackets of the Air Conditioning Outlet Extrusions between Body Station 360 and BS 907 - Inspections / Modification
US-2024-20-04	2024-10-29	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	Pacific Scientific Company: Rotary Buckle Assemblies - Inspection / Reidentifying / Replacing
2024-0210	2024-10-29	AIRBUS S.A.S.	A318, A319, A320, A321	Fuselage - Inner Cap and Frame Flange at Frame 68 Stringer 22 - Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0209	2024-10-28	AIRBUS HELICOPTERS	EC 120 B	Tail Rotor - Hub Body - Inspection / Replacement