



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-------------------------------------|--|---|
| 2024-0251-E | 2024-12-20 | SCHEMPP HIRTH FLUGZEUGBAU | Ventus Powered Sailplanes | Fuel - Wing Fuel Tank Hose - Inspections / Replacement Placards And Markings - Installation |
| 2024-0250 | 2024-12-20 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Tail Rotor - Rotor Head Bearing Stack of the Spindle-Sleeve Assembly - Life Limit |
| CF-2024-43 | 2024-12-19 | AIRBUS CANADA LP | BD-500 (A220 Series) | Time Limits / Maintenance Checks - Airworthiness Limitations |
| 2024-0218R1 | 2024-12-19 | SAFRAN HELICOPTER ENGINES | ARRIUS 2 | Engine - Gas Generator High-Pressure Turbine Blades - Replacement |
| CF-2024-42 | 2024-12-19 | BELL TEXTRON CANADA LTD (BTCL) | 427 | Main Rotor Drive System - Cracking of Transmission Oil Check Valve |
| 2024-0249 | 2024-12-19 | AIRBUS HELICOPTERS DEUTSCHLAND | EC135/635, MBB-BK 117 | Instruments - Warning Unit Emergency Off Switches - Operational Check |
| CF-2024-44 | 2024-12-19 | BELL TEXTRON CANADA LTD (BTCL) | 505 (Jet Ranger X) | Auto Flight - Wire Harness Chafing |
| 2024-0247 | 2024-12-18 | AIRBUS S.A.S. | A318, A319, A320, A321, A330, A340 | Flight Controls - Trimmable Horizontal Stabilizer Actuator - Modification |
| 2024-0248 | 2024-12-18 | AIRBUS S.A.S. | A350 | Landing Gear - Nose Landing Gear Lower Torque Link - Replacement / Life Limitation |
| 2024-0246 | 2024-12-17 | PIPISTREL VERTICAL SOLUTIONS d.o.o. | Virus SW | Electrical Power - Software and Data Recording System - Upgrade |
| 2020-0273-CN | 2024-12-17 | AIRBUS S.A.S. | A330, A340 | CANCELLED: Oxygen - Oxygen Supply Solenoid Valve - Inspection / Replacement |
| US-2024-23-03 | 2024-12-17 | BOEING | 737 | Flight Controls - Cruise Thrust Split Monitor (MONFD) of the Autothrottle (A/T) System - Inspection / Replacement |
| US-2024-23-11 | 2024-12-17 | BOEING | 737 | Flight Controls - Spoiler Control Wire Bundles - Inspection |
| CF-2024-31R1 | 2024-12-17 | BOMBARDIER | CL-600 (Challenger) | Flight Controls - Flap System On-Board Recorder (FSOBR) effects on Flap Control Unit |
| CF-2024-41 | 2024-12-16 | MHI RJ Aviation ULC | CL-600 (Regional Jet) | Time Limits/Maintenance Checks - Airworthiness Limitations (ALI) |
| 2024-0244 | 2024-12-13 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155 | Equipment / Furnishings - Hoist - Inspection |
| 2024-0245 | 2024-12-13 | AIRBUS HELICOPTERS | EC175 | Doors - Jettison Mechanism for Bad Weather Window Emergency Exits - Inspection |
| 2024-0243 | 2024-12-13 | AIRBUS HELICOPTERS | EC 120 B | Rotors Flight Control - Pilot Cyclic Stick Bonding Braid - Inspection |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|--|-------------------------------|---|
| 2024-0207R1 | 2024-12-12 | SAFRAN HELICOPTER ENGINES | ARRIEL 1 | [Correction] Engine - Gas Generator First Stage High Pressure Turbine Blades - Replacement |
| 2024-0242 | 2024-12-12 | SCHEMPP HIRTH FLUGZEUGBAU | Standard Cirrus | Flight Controls - Horizontal Tailplane Drive Lower Bearing - Modification |
| US-2024-24-05 | 2024-12-11 | BOEING | 767 | Equipment / Furnishings - Cargo Compartment Insulation Blankets - Replacement |
| US-2024-24-03 | 2024-12-11 | BOEING | MD-11 | Engine Exhaust - Thrust Reverser - Inspections |
| 2024-0236 | 2024-12-10 | CONTINENTAL AEROSPACE TECHNOLOGIES, GmbH | TAE125 | Engine - Engine Coolant Contamination - Inspection |
| 2024-0238 | 2024-12-10 | AIRBUS S.A.S. | A300-600, A300-600ST (Beluga) | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 4 / System Equipment Maintenance Requirements - Amendment |
| 2024-0239 | 2024-12-10 | TECNAM, Costruzioni Aeronautiche | P2010 | Flight Controls - Rudder Pedals Torque Tube Hinges - Modification |
| US-2024-24-01 | 2024-12-10 | BOEING | 757 | Fuselage - Upper Frame at the Frame Splices between Stringers - Inspections |
| 2024-0240 | 2024-12-10 | PILATUS AIRCRAFT LTD | PC-24 | Aeroplane Flight Manual - Section Normal Procedures / Flight Director Lateral Offset - Amendment |
| 2024-0237-E | 2024-12-09 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117 | Rotors Flight Control - Tail Rotor Actuator - Inspection |
| US-2024-24-11 | 2024-12-09 | CIRRUS DESIGN CORPORATION | SR20/22 | Engine Controls - Upper Power Lever - Inspections |