



Publ. number	Issue Date	TC Holder	Type	Subject
2025-0108	2025-05-08	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotors Flight Control - Ball Bearing Control System - Inspection
US-2025-07-03	2025-05-07	BOEING	737	Fuselage - Frame Fittings and Failsafe Strap Outboard Chords - Repetitive Inspections
2025-0105	2025-05-07	AIRBUS S.A.S.	A350	Aircraft Flight Manual - Derated Take-Off/Limitations - Amendment
2025-0106	2025-05-07	AIRBUS S.A.S.	A350	Wings - Pylon Primary Structure - Inspection
2025-0104	2025-05-07	AIRBUS S.A.S.	A330	Aircraft Flight Manual - Sections Limitations and Normal Procedures - Amendment Master Minimum Equipment List - Amendment Pneumatic - High Pressure Valve - Modification / Inspection / Replacement
2025-0051R1	2025-05-07	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND, LEONARDO S.p.A. HELICOPTERS	EC175, H160, SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, A109/A119, AB139/AW139, AW169, AW189	Equipment / Furnishings - Hoist - Replacement
2025-0107	2025-05-07	AIRBUS S.A.S.	A321	Fuselage - Frame 35 / Slidebox Junction - Inspection
CF-2025-22	2025-05-05	BELL TEXTRON CANADA LTD (BTCL)	407	Communication - Electrical harness chafing condition
CF-2025-23	2025-05-05	BELL TEXTRON CANADA LTD (BTCL)	505 (Jet Ranger X)	Nacelles/Pylons - Oil Cooler Fan Assembly Housing bracket cracking
US-2025-09-08	2025-05-05	BOEING	747	Stabilizers - Outboard Elevators - Maintenance Records Check / Inspection
CF-2025-21	2025-05-05	BELL TEXTRON CANADA LTD (BTCL)	407, 427	Main Rotor - Expandable Blade Bolt incorrect heat treatment
2025-0102	2025-05-05	PIAGGIO	P180	Hydraulic Power - Landing Gear Flexible Hoses - Modification
2025-0103	2025-05-05	ATR	ATR42, ATR72	Hydraulic Power - Main Hydraulic Pump - Master Minimum Equipment List Restriction
2025-0099	2025-04-30	AIRBUS S.A.S.	A350	Flight Controls - Flight Control Remote Module - Replacement
CF-2025-25	2025-04-30	AIRBUS CANADA LP	BD-500 (A220 Series)	Air Conditioning - Integrated Air System Control (IASC) - Cabin Pressure Sensors Drifting
CF-2025-24	2025-04-30	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Motive Flow Fuel-feed Tubes Damaged at Bonding Clamp and Clamp Block Locations Inside the Fuel Tank



Publ. number	Issue Date	TC Holder	Type	Subject
G-2025-0002	2025-04-30	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	[Correction] IPECO HOLDINGS Limited: Equipment / Furnishings - Pilot & Co-Pilot Seats - Inspection / Modification
2025-0100	2025-04-30	AIRBUS S.A.S.	A350	Engine Fuel and Control - Hydro-Mechanical Unit - Replacement / Modification
2025-0098	2025-04-29	AIRBUS HELICOPTERS	H160	Tail Rotor Drive - Tail Drive Line Rear Shaft and Damper - Inspections
2025-0097	2025-04-28	WSK PZL-SWIDNIK S.A.	PZL W-3A	Equipment / Furnishings - Hoist Support / Inspection / Replacement - Removal from Service
2025-0096	2025-04-28	AIRBUS S.A.S.	A319, A320, A321	Aircraft Flight Manual - Section Limitations - Amendment / Master Minimum Equipment List - Amendment / Pneumatic - High Pressure Bleed Valve - Replacement