



Publ. number	Issue Date	TC Holder	Type	Subject
2025-0197	2025-09-12	AIRBUS S.A.S.	A350	Flight Controls - Primary Flight Control System - Modification
CF-2025-47	2025-09-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Twisted Motive Flow (MF) Flexible Fuel Line
2025-0195	2025-09-12	AIRBUS S.A.S.	A300-600ST (Beluga)	Wings - Fuselage Frame 40 Lower Outboard Radius - Inspection
2025-0158R1	2025-09-12	AIRBUS S.A.S.	A318, A319, A320, A321	Landing Gear - Main Landing Gear Door Actuators - Inspections
2025-0151R2	2025-09-12	AIRBUS S.A.S.	A321	Equipment / Furnishings - Escape Slide Inflation Reservoir Regulator Valve - Inspection / Modification
2025-0196	2025-09-12	AIRBUS HELICOPTERS	EC175	Rotorcraft Flight Manual - Emergency Procedures Section - Amendment Integrated Modular Avionics - Ethernet Network - Inspection / Modification
2017-0158R2	2025-09-12	AIRBUS S.A.S.	A300-600	Wings - Fuselage Frame 40 Lower Outboard Radius - Inspection
2022-0168R1	2025-09-12	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND	H160, EC135/635, MBB-BK 117	Rotorcraft Flight Manual - Section Emergency Procedures - Amendment Integrated Modular Avionics - Ethernet Network - Inspection
BR-2025-09-02	2025-09-11	EMBRAER S.A.	EMB-135	Airworthiness Limitations (Certification Maintenance Requirements, Airworthiness Limitation Inspections, Fuel System Limitation Items, and Life Limited Items) - Revision
BR-2025-09-01	2025-09-10	EMBRAER S.A.	EMB-135, EMB-145	Airworthiness Limitations (Certification Maintenance Requirements, Airworthiness Limitation Inspections, Fuel System Limitation Items, and Life Limited Items) - Revision
US-2025-16-09	2025-09-10	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	Pacific Scientific Company: Rotary Buckle Assemblies - Inspection / Reidentification / Replacement
2025-0194	2025-09-10	AIRBUS S.A.S.	A380	Flight Controls - Primary System Flight Control Computer - Modification
Cf-2025-43	2025-09-09	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in the contiguous United States of America (U.S.) airspace
CF-2025-46	2025-09-09	BOMBARDIER	BD-700	Wings - Missing or Under Torqued Fasteners on Slat 2 Cove Rib 6 Bracket



Publ. number	Issue Date	TC Holder	Type	Subject
2025-0192	2025-09-08	AIRBUS S.A.S.	A350	Doors - Passenger / Crew Door Girt Bar Fitting Assemblies - Inspection
US-2025-17-16	2025-09-08	INTERNATIONAL AERO ENGINES AG	V2500-()5	Turbine Engine - Airworthiness Limitations Section - Revision
2025-0193	2025-09-08	AIRBUS S.A.S.	A320, A321	Fuselage - Forward and Aft Upper Corner Bulk Cargo Door Section 16 and 17 - Inspection / Modification
2024-0202R1	2025-09-08	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Fuel Control Unit - Replacement
2025-0190	2025-09-04	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	[Correction] Engine - Low Pressure Turbine Seal Panel - Modification / Inspection
2025-0191	2025-09-04	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
CF-2025-45	2025-09-03	AIRBUS CANADA LP	BD-500 (A220 Series)	Electrical System Installation - Lavatory A Maintenance Panel - Harnesses Inadequately Secured
ISR-I-05-2025-09-1	2025-09-02	GULFSTREAM (GALP)	G200, GALAXY	G200 Airworthiness Limitations Section (ALS) Revision
2025-0167R1	2025-09-02	AIRBUS S.A.S.	A318, A319, A320, A321	Landing Gear - Main Landing Gear Aft Pintle Pin - Replacement
2025-0189	2025-09-02	AIRBUS S.A.S.	A318, A319, A320, A321	Fuselage - Centre Fuselage / Main Landing Gear Door Keel Beam Hinge and Actuator Fittings - Inspection
CF-2025-44	2025-09-01	PRATT & WHITNEY CANADA	PW150	PW150A Full Authority Digital Electronic Control (FADEC) Software Upgrade to Minimize Risk of Aircraft Jet Pipe Fire
2025-0188	2025-09-01	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Equipment / Furnishings - Large Hook Damper Assembly - Modification