



Publ. number	Issue Date	TC Holder	Type	Subject
ISR-I-35-26-01-01	2026-01-01	BOEING, ISRAEL AEROSPACE INDUSTRIES LTD	747, CAA Israel STC SA151, CAA Israel STC SA152, EASA STC 10014423, EASA STC 10015911	Potential of arcing, fire and/or loss of crew oxygen supply due to insufficient clearances between electrical wiring and flexible oxygen hose
2025_0298_E	2025-12-23	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Main Rotor - Swashplate - Inspection
2025-0297	2025-12-23	APPLIANCES	ATA 35 OXYGEN	AEROSPACE & DEFENSE OXYGEN SYSTEMS SaS (Part of SAFRAN AEROSYSTEMS): Portable Breathing Equipment - Removal From Service
2025-0296	2025-12-23	AIRBUS HELICOPTERS	H160	Tail Rotor Drive - Tail Drive Line Rear Shaft and Damper - Inspections
2025-0294	2025-12-22	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	B/E AEROSPACE FISCHER GmbH - Equipment / Furnishings - Medical Seats - Modification
2025-0295	2025-12-22	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	AIRCRAFT CABIN MODIFICATION - Equipment / Furnishings - Pallet Net - Limitation