



| Publ. number   | Issue Date | TC Holder                                | Type                                | Subject   |
|----------------|------------|--|-------------------------------------|---|
| 2026-0083      | 2026-04-22 | AIRBUS S.A.S.                            | A319, A320, A321                    | Stabilizers - Rudder Overweight Detection - Inspection  |
| BR-E2026-04-02 | 2026-04-20 | EMBRAER                                  | EMB-545/-550 (Legacy 500)           | Pitch Trim Actuator - Inspection / Replacement  |
| 2026-0081      | 2026-04-20 | AIRBUS HELICOPTERS DEUTSCHLAND           | EC135/635, MBB-BK 117               | Instruments - Warning Unit Emergency Off Switches - Operational Check / Replacement   |
| 2026-0082      | 2026-04-20 | AIRBUS S.A.S.                            | A350                                | Flight Controls - Aileron, Elevator and Rudder Servocontrols - Replacement  |
| 2026-0080      | 2026-04-17 | AIRBUS HELICOPTERS DEUTSCHLAND           | EC135/635                           | Aircraft Flight Manual - Emergency, Malfunction and Normal Procedures - Amendment   |
| 2026-0079      | 2026-04-17 | AIRBUS S.A.S., LUFTHANSA TECHNIK AG      | A319, A320, A321, EASA STC 10049524 | Communications - IFE Control and Service Box - Modification   |
| 2026-0055R1    | 2026-04-14 | AIRBUS S.A.S.                            | A319, A320, A321                    | Fuselage - Forward Fuselage Skin Panels - Inspection  |
| 2026-0077      | 2026-04-14 | CONTINENTAL AEROSPACE TECHNOLOGIES, GmbH | TAE125                              | Engine - Engine Coolant Contamination - Inspection  |
| CF-2025-54R1   | 2026-04-13 | DE HAVILLAND AIRCRAFT OF CANADA LTD.     | DHC-8                               | Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace affected by 5G C-Band wireless signals |
| 2026-0078-E    | 2026-04-13 | AIRBUS HELICOPTERS DEUTSCHLAND           | MBB-BK 117                          | Main Rotor Drive - Rotor Hub-Shaft - Inspection   |