



Publ. number	Issue Date	TC Holder	Type	Subject
2026-0129	2026-07-03	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor Drive - Main Gearbox Flexible Mounting Plate - Maintenance Task
2026-0123	2026-07-03	GE AVIATION CZECH	H75, H80, H85	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2025-0094R1	2026-07-03	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Electrical Power - Overhead Panel Wires Interference - Inspection / Modification
2025-0171R2	2026-07-03	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - High Pressure Turbine Rotor Stage 1 Blade - Inspection
CF-2026-26	2026-07-03	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Corrosion on Waste Box, Waste Access Doubler and Waste Service Door of Aft Waste Service Port
2026-0128	2026-07-02	SAFRAN HELICOPTER ENGINES	ARRIUS 1	Engine Fuel & Control - Hydromechanical Metering Unit - Replacement
US-2026-13-13	2026-07-01	BOEING	737	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
US-2026-13-11	2026-07-01	BOEING	787	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
US-2026-13-14	2026-07-01	BOEING	747	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
US-2026-13-15	2026-07-01	BOEING	707, 717, 727, DC-10, DC-8, DC-9, MD-10, MD-11, MD-88, MD-90	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
US-2026-13-16	2026-07-01	BOEING	757, 767	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
US-2026-13-17	2026-07-01	BOEING	737	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
2026-0124	2026-07-01	TECNAM, Costruzioni Aeronautiche	P2006T	Flight Controls - Aileron Hinge / Cotter Pins - Inspection
US-2026-13-02	2026-07-01	APPLIANCES	ATA 31 INSTRUMENTS, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED



Publ. number	Issue Date	TC Holder	Type	Subject
US-2026-13-10	2026-07-01	BOEING	747, 777	Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace - Amendment
2026-0127	2026-06-30	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Main Rotor - Swashplate - Inspection
2026-0125R1	2026-06-30	DIAMOND AIRCRAFT INDUSTRIES	DA 42	Landing Gear - Nose landing Gear Hydraulic Actuator Rod End - Inspection
2026-0126-CN	2026-06-30	DASSAULT AVIATION	Falcon 2000, Mystère-Falcon 900	CANCELLED: Fire Protection - Safe Selector Switches on the Control Panel with Metallic Snap Wire
2026-0122	2026-06-26	AIRBUS S.A.S.	A350	Flight Controls - Droop Nose Geared Rotary Actuator Ring - Inspection / Replacement
2025-0288R1	2026-06-26	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 700	Engine - Low Pressure Compressor Blades - Removal from Service
CF-2026-33R1	2026-06-25	AIRBUS CANADA LP	BD-500 (A220 Series)	Pneumatic - High Pressure Valve - Butterfly Clip Failure
2025-0237R1	2026-06-24	AIRBUS S.A.S.	A318, A319, A320, A321	[Correction] Equipment / Furnishings - 80 VU Rack Attachments - Inspection / Repair
2026-0121-E	2026-06-24	BRP-ROTAX GmbH & Co KG	912 A, 912 F, 912 S, 912 iSc, 914 F	Engine - Propeller Gearbox - Inspection
2026-0120	2026-06-23	AIRBUS S.A.S.	A319, A320, A321	Fuselage - Lateral Window Frame - Inspections
CF-2026-07R1	2026-06-22	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing
2026-0118	2026-06-22	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Rotors Flight Control - Tail Rotor Actuator - Inspection
CF-2026-27	2026-06-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Nacelles/Pylons - Upper and Side Pylon Link Assemblies - Replacement
2026-0119-E	2026-06-22	AIRBUS S.A.S.	A380	Wings - Wing Mid Spars - Inspection
CF-2026-09R1	2026-06-22	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing