

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No : 2007-0034</p> <p>Date: 22 February 2007</p>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
Type Approval Holder's Name :	Type/Model designation(s) :	
EADS SOCATA	TB 9, TB 10 and TB 200	
TCDS Number: DGAC France No 165		
Foreign AD: Not applicable		
Supersedure: Not applicable		
ATA 05	Time Limits - Airworthiness Limitations – New Life Limit for Engine and Nose Landing Gear Mounts	
Manufacturer:	EADS SOCATA (formerly SOCATA)	
Applicability:	TB 9, TB 10 and TB 200 aircraft, all serial numbers.	
Reason:	<p>The aim of this Airworthiness Directive (AD) is to introduce a new life limit for engine and Nose Landing Gear (NLG) mounts installed on EADS SOCATA TB 9, TB 10 and TB 200 airplanes, as defined in the updated Airworthiness Limitations Section (ALS) of the relevant Aircraft Maintenance Manuals (AMM).</p> <p>This AD requires introduction of the new 10 000 Flight Hour life limit for engine and NLG mounts into the operator's maintenance program through the Revision 18 of the AMM.</p>	
Effective Date:	08 March 2007	
Compliance:	<p>From the effective date of this AD:</p> <ol style="list-style-type: none"> 1. Update the AMM by inserting their respective Revision 18. 2. Modify accordingly the operator's maintenance program to comply with all limitations from the ALS of the respective Maintenance Manual Chapter 4 given in reference. 	

Ref. Publications:	<ul style="list-style-type: none">- EADS SOCATA TB 9 Maintenance Manual Chapter 4 Revision 18;- EADS SOCATA TB 10 Maintenance Manual Chapter 4 Revision 18;- EADS SOCATA TB 200 Maintenance Manual Chapter 4 Revision 18, or later approved revisions.
Remarks :	<ol style="list-style-type: none">1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD.2. This AD was posted as PAD 06-260 for consultation on 05 December 2006 until 05 January 2007. No comments were received during the consultation period.3. Enquiries regarding this Airworthiness Directive should be referred to the AD Focal Point - Certification Directorate, EASA. E-mail: ADs@easa.europa.eu .4. For any question concerning the technical content of the requirements in this AD, please contact: EADS SOCATA – Direction des Services – 65921 TARBES CEDEX 9 – France Ph.: +33 (0)5 62.41.73.00 ; Fax: +33 (0)5 62.41.76.54