

## **PAD 08-089 WITHDRAWAL STATEMENT**

EASA has withdrawn PAD 08-089 for the following reasons:

- AIRBUS, the approval holder of the A318, A319, A320 and A321 family of aeroplanes, the type design to which PAD 08-089 applies, has informed EASA that the operators of remaining unmodified aeroplanes have now accomplished Service Bulletin (SB) A320-28-1151; none of the affected Twin Motor Actuators are in service anymore;
- Based on the above statement, EASA is confident that the Airbus campaign that was initiated in 2007 has had the desired results and the unsafe condition addressed by PAD 08-089 no longer exists.

For the above mentioned reasons, PAD 08-089 is hereby withdrawn.

Signed in Cologne, 22 October 2009

Phil Blagden  
Manager, Section Large Aeroplanes  
EASA Certification Directorate