

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.


Translation of 'Consigne de Navigabilité' ref. : 84-73-(AB)
In case of any difficulty, reference should be made to the French original issue.

SECURAIGLON

(FORMERLY L'AIGLON) SAFETY BELTS

MODEL 343

The present Airworthiness Directive applies to SECURAIGLON (formerly L'AIGLON) safety belts equipped with L'AIGLON buckles models 343, 343A, 343B and 343C manufactured prior to 1982 and which do not bear the following punch marking (**See note**) :



In order to prevent any possibility of jamming in the locked position, above mentioned buckles must be modified in accordance with TRW Service Bulletin n° 1 (or later approved revision) within the next 6 months after effective date of this Airworthiness Directive.

After embodiment of above mentioned S B, identify modified buckles by adding the letter "M" with a punch after model designation (exemple : 343M, 343AM, 343BM, 343CM).

NOTE: Model designation and year of manufacture are shown on the back of the buckle body.

Buckle models 343D and 343-1 are not affected by the present Airworthiness Directive.

EFFECTIVE DATE : MAY 16, 1984

V.K

May 09, 1984

SECURAIGLON
(Formerly L'aiglon) safety belts

84-73-(AB)