

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

**Translation of 'Consigne de Navigabilité' ref. : 90-027-103(B)**  
**In case of any difficulty, reference should be made to the French original issue.**

## AIRBUS INDUSTRIE

### A300 and A300-600

Air Cruisers emergency escape slides

This Airworthiness Directive applies to the AIRBUS INDUSTRIE models A300 B2-1C, A300 B4-2C, A300 B4-200 and A300 B4-600 series airplanes equipped with Air Cruisers escape slides P/N D31021-101 and D31021-103.

In order to prevent an incorrect deployment of the emergency escape slides, the following measures are rendered mandatory within a period of 6 months after the effective date of this Airworthiness Directive :

- Modify and reidentify the Air Cruisers emergency escape slides P/N D31021-101 and D31021-103 that have serial numbers less than 223 in accordance with AIRBUS INDUSTRIE Service Bulletins A300-25-430 or A300-25-6024 and Air Cruisers Service Bulletin 001-25-8.

Ref. AIRBUS INDUSTRIE Service Bulletins A300-25-430, A300-25-6024  
Aircruisers Service Bulletin 001-25-8

The present AD is the subject in FRG of LTA n° 90-41

**EFFECTIVE DATE : MARCH 03, 1990**

e/C

February 21, 90

**AIRBUS INDUSTRIE**  
**A300 and A300-600 airplanes**

**90-027-103(B)**