

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 90-135-113(B) R1  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A310 and A300-600 airplanes

Emergency oxygen containers

The present Airworthiness Directive applies to AIRBUS INDUSTRIE A310 aircraft models -204, -304, -324 and A300-600 models B4-603, B4-605R, B4-622, B4-622R.

In order to prevent the non-opening of the emergency oxygen container doors located in the passenger service unit, the following measure is rendered mandatory on effective date of this Airworthiness Directive :

- Unless already accomplished and before July 31, 1991 carry out modification and test of the emergency oxygen containers in accordance with AIRBUS INDUSTRIE Service A300-35-2002R2 or A300-35-6001R2.

**NOTE :** The present Airworthiness Directive is not applicable to airplanes which have already been modified in accordance with Service Bulletins A310-35-2002, A310-35-2002 R1, A300-35-6001 and A300-35-6001 R1.

Ref. : AIRBUS INDUSTRIE Service Bulletins A310-35-2002 R2  
and A300-35-6001 R2  
and previous revisions.

**EFFECTIVE DATE : MAY 12, 1991**

y/C

May 02, 1991

AIRBUS INDUSTRIE  
A310 and A300-600 airplanes

90-135-113(B) R1