AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are madatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref.: 97-151-224(B) R1
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A300 Aircraft

Lavatories - Pressure difference between toilet and cabin

This Airworthiness Directive applies to AIRBUS INDUSTRIE A300 aircraft, all certified models and all serial numbers, equipped with MONOGRAM type toilets, on which:

- AIRBUS INDUSTRIE serial modification n° 4256 or 2120
- AIRBUS INDUSTRIE Service Bulletin A300-38-034 rev. 3 would not have been embodied.

In order to prevent excessive differential pressure between the cabin and the toilet which is directly vented to outside the aircraft which could cause considerable suction on the occupant, the following measures are rendered mandatory from the effective date of this Airworthiness Directive:

rendered mandatory from the effective date of this Airworthiness Directive :
- Before December 31, 1998, modify the toilets in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletin A300-38-034 rev. 3.
This Revision 1 replaces the original AD 97-151-224(B) dated July 16, 1997.
Ref.: AIRBUS INDUSTRIE Service Bulletin A300-38-034 rev. 3 (or any other later approved revision)

EFFECTIVE DATES:

Original AD: JULY 26, 1997

July 01, 1998 AIRBUS INDUSTRIE 97-151-224(B) R1

	GSAC	AIRWORTHINESS DIRECTIVE		ref. :	97-151-224(B) R1	Page n°	2
R			Revision 1 :	JULY 1	, 1998		