

**State of Israel  
Ministry of Transport  
Civil Aviation Administration**

**AD 28-02-03-15**

**Date: March 26, 2002**

**AIRWORTHINESS DIRECTIVE**

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** Israel Aircraft Industries Models Galaxy serial numbers 004-056 & Gulfstream 200, serial numbers 057-061, certificated in any category.
- SUBJECT:** Inspection of evidence / accumulation of fuel in the service compartment.
- REASON:** To preclude possible fire in the aft service compartment.
- ACTION:** Inspect and repair the service compartment access door area for evidence of fuel accumulation per Galaxy Alert service bulletin no. Galaxy-28A-130.
- COMPLIANCE:** Prior to next flight, recurrent inspection every 5 flights.

**EFFECTIVE DATE:** March 26, 2002.

**FOR FURTHER INFORMATION CONTACT:** Mr. T. Bar-Am, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.  
Telephone: 972-3-9774537, Fax: 972-3-9774592, e-mail: baramt@mot.gov.il