

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 94-195(B)
In case of any difficulty, reference should be made to the French original issue.**

CFM INTERNATIONAL

CFM56-3C-1 turbo fan engines

Fan disk

The present Airworthiness Directive applies to CFM56-3C-1 turbo fan engines installed on BOEING 737 aircraft series 300, 400 and 500 (or others).

The life limits of the fan disks referenced by P/N's :

335-014-509-0
335-014-511-0

have been revised and reduced to 20100 cycles (instead of 30000) if the engine is used at the class of thrust C.
(See Engine Shop Manual CFM-TP-SM5 chapter 05-11-01, revision 38 dated June 01, 1994 (or later)).

EFFECTIVE DATE : SEPTEMBER 10, 1994

n/E

August 31, 1994

CFM INTERNATIONAL
CFM56-3C-1 turbofan engines

94-195(B)