



No.	CF-2008-17R2	1/1
Issue Date	30 January 2013	

AIRWORTHINESS DIRECTIVE

The following airworthiness directive (AD) may be applicable to an aircraft which our records indicate is registered in your name. ADs are issued pursuant to **Canadian Aviation Regulation (CAR) 521 Division X**. Pursuant to **CAR 605.84** and the further details of **CAR Standard 625, Appendix H**, the continuing airworthiness of a Canadian registered aircraft is contingent upon compliance with all applicable ADs. Failure to comply with the requirements of an AD may invalidate the flight authorization of the aircraft. Alternative means of compliance shall be applied for in accordance with **CAR 605.84** and the above-referenced **Standard**.

This AD has been issued by the Continuing Airworthiness Division (AARDG), National Aircraft Certification Branch, Transport Canada, Ottawa, telephone 613 952-4357.

Number: CF-2008-17R2

Subject: Tension-Torsion Straps Failure

Effective: Upon Receipt

Cancellation: Cancels Airworthiness Directive CF-2008-17R1, dated 26 May 2008

Applicability: Eurocopter Canada Ltd. (formerly MBB Canada Ltd.) Model BO 105 LS-A3 helicopters

Compliance: As indicated below.

Background: Recently, the European Aviation Safety Agency (EASA) issued AD 2013-0015 that includes the corrective actions mandated by AD CF-2008-17R1. Because EASA is presently the authority responsible for the Type Design of this helicopter model, AD CF-2008-17R1 becomes redundant and needs to be cancelled.

Corrective Actions: Transport Canada AD CF-2008-17R1 is cancelled as of the effective date of this AD. Operators of the affected helicopters shall comply with EASA AD 2013-0015.

Authorization: For the Minister of Transport, Infrastructure and Communities,

ORIGINAL SIGNED BY

Philip Tang
Acting Chief, Continuing Airworthiness

Contact: Bogdan Gajewski, Continuing Airworthiness, Ottawa, telephone 613-952-4357, facsimile 613-996-9178 or e-mail ADs@tc.gc.ca or any Transport Canada Centre.

Pursuant to **CAR 202.51** the registered owner of a Canadian aircraft shall, within seven days, notify the Minister in writing of any change of his or her name or address.

To request a change of address, contact the **Civil Aviation Communications Centre (AARC)** at **Place de Ville, Ottawa, Ontario K1A 0N8**, or **1-800-305-2059**, or www.tc.gc.ca/civilaviation/communications/centre/address.asp