

EASA Safety Information Section



No actual AD document exists for this AD, other than the 'Mandatory' service bulletin (latest revision applies) that is the subject of the AD.

This was the method employed by the CAA of the United Kingdom (UK) to mandate inspections and modifications on products, parts and appliances of UK origin until 15 July 2003, when AD G-2003-0001 was issued.

Until that date, each AD was only a reference number in a book, [CAP476](#), listing the mandatory service publications for each type design. Each referenced 'Mandatory' service bulletin contains the applicability (Type(s), Model(s) and s/n), the required action(s) and compliance time(s), as agreed and approved by the CAA UK at the time.

Please note that, for reasons of consistency, each CAA UK AD number, allocated before AD G-2003-0001, has received the prefix G- for the EASA website database record. This also identifies the original State of Design (G = Great Britain) of the product(s), part(s) or appliance(s) to which the AD applies.

For any question concerning the technical content of the requirements in this AD, please contact

UK Production:

Messier-Dowty Ltd
Cheltenham Road
Gloucester
GL2 9QH

Equipment Design:

MESSIER-BUGATTI-DOWTY
Inovel Parc Sud
78141 Velizy-Villacoublay
France