

2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full consultation process.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: Leonardo S.p.A. Helicopters, Customer Support & Services, Product Support Engineering & Licenses DPT, Via Giovanni Agusta 520, 21017 Cascina Costa di Samarate (VA) – Italy, Telephone: +39 0331 255036, Fax: +39 0331 225988, E-mail: PSE_AW169.MBX.AW@leonardocompany.com.

Superseded

