


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	<p>PAD No.: 13-031</p> <p>Date: 06 February 2013</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>	
Type Approval Holder's Name :	Type/Model designation(s) :
AIRBUS	A318, A319, A320 and A321 aeroplanes
TCDS Number:	EASA.A.064
Foreign AD:	Not applicable
Supersedure:	This AD supersedes DGAC France AD F-2005-101 (EASA approval 2005-5886) dated 22 June 2005.
ATA 05	Time Limits and Maintenance Checks – Certification Maintenance Requirements – ALS Part 3 – Amendment
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.
Reason:	<p>The airworthiness limitations for Airbus aeroplanes are currently published in Airworthiness Limitations Section (ALS) documents. The airworthiness limitations applicable to the Certification Maintenance Requirements (CMR) were previously specified in AIRBUS A318/A319/A320/A321 CMR document referenced AI/ST4/993.436/88.</p> <p>DGAC France issued AD F-2005-101 (EASA approval 2005-5886) to require compliance with the maintenance tasks as specified in that document.</p> <p>Since that AD was issued, the CMR tasks are specified in Airbus A318/A319/A320/A321 ALS Part 3, which is approved by EASA. The original issue of this document introduced more restrictive maintenance requirements and/or airworthiness limitations. Failure to comply with the maintenance requirements contained in this document could result in an unsafe condition.</p> <p>For the reasons described above, this AD supersedes DGAC France AD F-2005-101 and requires the implementation of the instructions and airworthiness limitations as specified in Airbus A318/A319/A320/A321 ALS Part 3 Revision 01.</p>

Effective Date:	[TBD: 14 days after Final AD issue date]
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) After the effective date of this AD, within the compliance times defined in the Record of Revisions (ROR) pages of Airbus A318/A319/A320/A321 ALS Part 3 Revision 01, accomplish all applicable maintenance tasks, depending on aeroplane configuration, as included by reference in the ROR of ALS Part 3 Revision 01. (2) If, during accomplishment of any task as required by paragraph (1) of this AD, discrepancies are detected, within the applicable compliance time specified in the Airbus maintenance documentation, accomplish the applicable corrective actions in accordance with instructions specified (or incorporated by reference) in the applicable Airbus maintenance documentation. <p>If no compliance time is identified in Airbus maintenance documentation, before next flight, accomplish the applicable corrective action(s), or contact Airbus for approved instructions and within the compliance time specified in those instructions, accomplish those instructions accordingly.</p> <p>If any of the discrepancies detected during accomplishment of any task, as required by paragraph (1) of this AD, is not identified in the Airbus maintenance documentation, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.</p> (3) Compliance with the requirements of paragraph (1) of this AD can be demonstrated by: <ol style="list-style-type: none"> (3.1) Revising as follows the approved Aircraft Maintenance Programme (AMP), on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane: <p>Incorporate all instructions and airworthiness limitations specified in ALS Part 3 Revision 01, as relevant to the aeroplane configuration, and</p> (3.2) Complying with the approved AMP described in paragraph (3.1) of this AD.
Ref. Publications:	<p>Airbus A318/A319/A320/A321 ALS Part 3 Revision 01, approved by EASA on 15 June 2012.</p> <p>The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.</p>
Remarks :	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 06 March 2013. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51; E-mail: account.airworth-eas@airbus.com.