



EASA Safety Information Notice

No.: 2008-26

Issued: 01 April 2008

Subject: Nichols Airborne F7-51 series Electronic Controllers that have been improperly maintained and returned to service

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. 2008-200700130.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 through 6 of this notice) as a result of an investigation that revealed that certain Nichols Airborne F7-51 series electronic controllers have been improperly maintained and returned to service, contrary to regulations.

Applicability: Nichols Airborne F7-51 series electronic controllers held as spares and identified in the attached FAA UPN; and any Hawker Beechcraft (formerly Raytheon Aircraft Company; Beech Aircraft Corporation) Super King Air (any Model) series aircraft which have Nichols Airborne F7-51 series electronic controllers, as identified in the attached FAA UPN, installed.

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.
E-mail: ADs@easa.europa.eu .