

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE SECRETARIAT GENERAL
FOR CIVIL AVIATION

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

AEROSPATIALE HELICOPTERS -
SA 341 G GAZELLE

MAIN GEAR BOX FORWARD "A" FRAME

In addition to the modification already applied to the M.G.B. forward "A" frame (Airworthiness Directive 73-47-4, par. b refers), a further modification consisting in making two additional flats at the top of the "A" frame has been rendered mandatory.

This modification is to be applied on the next scheduled inspection of the airframe or within the next 100 operating hours at the latest.

After incorporation of this modification, the P/N of these forward "A" frames becomes :

341A.38.1019.12 or .14 or .16.

REFERENCE : AEROSPATIALE SERVICE-BULLETIN SA 341 GAZELLE No 01-02,
Revision 1.

Date : 27.11.73

Material : AEROSPATIALE HELICOPTER -
SA 341 G GAZELLE

Reference : 73.128.8

Translation of "Consigne de Navigabilité
Réf. 73-128-8 "

In case of any difficulty, reference
should be made to the French original text.