

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 85-214-21(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE HELICOPTERS SUPER PUMA AS 332 C AND AS 332 L

Deicing system

The present Airworthiness Directive applies to AEROSPATIALE SUPER PUMA AS 332 C and AS 332 L helicopters equipped with the optional deicing system P/N 332A82.4300 (removable parts) and P/N 332A82.4301 (fixed parts).

Following incidents occurred in service, a telegraphic Airworthiness Directive had been issued on October 15, 1984, by DGAC to render mandatory a daily visual inspection of the main rotor head top fairing and the removal from service of the tail rotor deicing system.

Since then, operators have removed the complete deicing system and complementary studies have led to important modifications involving a change of the deicing system design and of its limitations.

Consequently, the present Airworthiness Directive confirms that previous deicing system P/N 332A82.4300 (removable parts) and P/N 332A82.4301 (fixed parts) is no longer authorized for use.

NOTE 1 : The new deicing system P/N 332A82.4300.02 (removable parts) and P/N 332A82.4301.11 (fixed parts) may be installed and can be used in accordance with approved Flight Manual Supplement n° 10-13, Revision 4, and in conformity with prescriptions of the Master Servicing Recommendations, chapter 5.99 (Airworthiness Limitations), Revision 13 (AS 332 C) or Revision 11 (AS 332 L), or later approved revisions of those documents.

NOTE 2 : The new deicing system P/N 332A82.4300.02 (removable parts) and P/N 332A82.4301.11 (fixed parts) is obtained from the previous system by embodiment of modifications prescribed by AEROSPATIALE Service Bulletin AS 332 n° 01-09.

Dated : Dec. 18, 85

AEROSPATIALE HELICOPTERS
SUPER PUMA AS 332 C AND AS 332 L

Ref. : 85-214-21(B)

NOTA 3 : The deicing bundles P/N 330A63.6223.06 and P/N 330A63.6223.07 are not authorised for use at temperatures below minus 30 degrees C.

Ref. : AEROSPATIALE Service Bulletin AS 332 n° 01-09

Cancels and replaces telegraphic Airworthiness Directive issued October 15, 1984

EFFECTIVE DATE : DECEMBER 26, 1985