

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 86-161-5(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE SN 601 Aircraft

Fuel filters

The present Airworthiness Directive applies to AEROSPATIALE SN 601 aircraft, all serial numbers, which are not equipped with fuel heaters (modification 1390 or Service Bulletin n° 73-1)

In order to reduce risks of non by-pass, in case of visual clogging indicator sticking, replace, unless already accomplished, the fuel filters LE BOZEC & GAUTIER part number 433-E25-2 by filters part number 433-E25-21, before but not later than 31th December 1986, in accordance with the instructions of Service Bulletin Aerospatiale n° 28-10.

=====

Cf. : Service Bulletin Aerospatiale n° 28-10

=====

EFFECTIVE DATE : October 25, 1986

Date Oct.15,86

AEROSPATIALE SN 601 Aircraft

Ref. : 86-161-5(B)