

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 90-029-027(B)
In case of any difficulty, reference should
be made to the French original issue.

ATR 42-300 and -320 aircraft

Emergency lighting

The present Airworthiness Directive applies to ATR 42-300 and -320 aircraft all serial numbers without Service Bulletin ATR 42-33-0017 (Mod 2404) embodied.

In order to conform the airplane to the certification requirements of JAR 25 change 8 paragraph 25-812(e)(3), the following measure is rendered mandatory :

- Before December 31, 1990, in order to allow automatic emergency lighting when the flight compartment control-switch is in the "ARM" position in case of loss of the normal electrical power, modify the emergency lighting control wiring as per Service Bulletin ATR 42-33-0017 (Mod 2404).

Ref. : Service Bulletin ATR 42-33-0017 (Mod 2404)

EFFECTIVE DATE : MARCH 3, 1990

February 21, 90

ATR 42-300 and -320 aircraft

90-029-027(B)