

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 96-256-068(B)
In case of any difficulty, reference should be made to the French original issue.**

ATR

ATR 42 aircraft

Stick shaker/pusher system

The present Airworthiness Directive applies to ATR 42 aircraft models -200, -300 and -320 on which modification 4700 or Service Bulletin ATR 42-27-0083 has not been embodied.

In order to reinforce the stick shaker/pusher system protection against all inadvertent tripping of the stick pusher test function, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- Before February 15, 1997, modify the test system of this function in compliance with the instructions given in Service Bulletin ATR 42-27-0083.

REF. : Service Bulletin ATR 42-27-0083

EFFECTIVE DATE : NOVEMBER 16, 1996

n/JPD

November 06, 1996

ATR
ATR 42 aircraft

96-256-068(B)