

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 2001-316-079(A)  
In case of any difficulty, reference should be made to the French original issue.

## EUROCOPTER

### AS 332 helicopters

Skis installation (ATA 05, 32)

1. EFFECTIVITY:

AS 332 helicopters, versions L and L1 equipped with "SEFA" skis.

2. REASON:

This Airworthiness Directive renders the VNE and the maximum taxiing speed limitations mandatory for helicopters equipped with skis.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

The following actions are rendered mandatory from the effective date of this Airworthiness Directive:

- before the next flight, incorporate referenced supplement SUP. 10.14 (Skis Installation) into the aircraft Flight Manuals,
- as from the next flight, comply with the speed limitations specified in this supplement.

REF.: Aircraft Flight Manuals supplement SUP. 10.14 Normal Revision 2 Issue 2.

EFFECTIVE DATE :

On receipt from JULY 25, 2001

d/DJ

July 25, 2001

EUROCOPTER  
AS 332 helicopters

2001-316-079(A)