**GSAC** 

# **AIRWORTHINESS DIRECTIVE**

## released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-501-001(A) R1 In case of any difficulty, reference should be made to the French original issue.

## **EUROCOPTER**

## EC 130 helicopters

Hydraulic power - Hydraulic fluid (ATA 29)

## 1. **EFFECTIVITY**:

This Airworthiness Directive applies to EC 130 B4 helicopters pre MOD 073718.

**<u>Caution</u>**: This Airworthiness Directive is intended for maintenance personnel and crews.

## 2. REASONS:

This Airworthiness Directive (AD) is issued to prohibit the use of hydraulic fluid MIL-H-5606 (NATO code H-515) for servo-controls, because this fluid is not certificated.

Revision 1 of this AD covers EUROCOPTER EC 130 Alert Telex No. 29A001.

## 3. MANDATORY ACTIONS AND COMPLIANCE TIME:

- **3.1.** The use of fluid MIL-H-5606 (NATO code H515) has been prohibited since the effective date of the original issue of this AD.
- **3.2.** From the effective date of this AD Revision 1:
  - **3.2.1.** Before the next flight, modify the labels on the hydraulic reservoirs in compliance with the instructions described in paragraph 2.B.1 of referenced EC 130 Alert Telex No. 29A001.
  - **3.2.2.** For operators having used hydraulic fluid MIL-H-5606, no later than within the next 50 flight hours, drain and flush the hydraulic systems and replenish them with hydraulic fluid MIL-H-83282, in compliance with the instructions described in paragraph 2.B.2 of the referenced Alert Telex.
- **3.3.** Before installation on aircraft of the hydraulic spare reservoirs, modify the labels of the reservoirs in compliance with the instructions described in paragraph 2.B.1 of the referenced Alert Telex.

.../...

n/DJ

GSAC	AIRWORTHIN	ESS DIRECTIV	E	ref.:	2001-501-001(A) R1	Page n°	2
Note: The the N	referenced revisi MIL-H-5606 fluid.	on ITR 1C of the	e EC 130 B	4 Flight N	fanual incorporates the	use prohibition	ı of
	<u>REF</u> .:	EC 130 B4 Flig EUROCOPTE	ght Manual R EC 130	Revision Alert Tele	No. ITR 1C. x No. 29A001.		
This Revision	on 1 replaces ori	ginal AD 2001-50 —	01-001(A) (	dated Oct	ober 31, 2001.		
I			issued o	ipt of the	e telegraphic AD BER 09, 2001		