

**State of Israel
Ministry of Transport
Civil Aviation Authority**

AD ISR I-32-24-10-01

Date: 06 OCT, 2024

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority of Israel in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list as under your registration or you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: All G150 Model Aircrafts

SUBJECT: **G150 nose landing gear actuator to strut attachment pin inspection & replacement**

REASON: Service report of failure of Nose landing gear actuator to strut attachment pin P/N 3-2247-0500-008.

ACTION: G150 operators to incorporate AMM Revision 29 or later CAAI approved revision (pin life limit added to section 05-10-10 of the G150 AMM).

COMPLIANCE: Unless already accomplished, comply with this AD within three (3) months from the effective date of this AD.

EFFECTIVE DATE: October 06, 2024.

FOR FURTHER INFORMATION CONTACT: Mr. Shaul Pascal, A/C certification department, CAAI - P.O. Box 1101, 3 Golan Street, Airport City, Israel, 70151, Telephone: 972-3-9774853, E-mail: pascals@mot.gov.il