

M.A.L.

(MEDEDELINGEN
AAN NEDERLANDSE
LUCHTVARENDEN
EN EIGENAREN VAN
LUCHTVAARTUIGEN)

NEDERLAND

RIJKSLUCHTVAARTDIENST

LUCHTVAARTINLICHTINGDIENST

70/70

9 jun

(AIR 407)

PLESMANWEG 1—6, 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZINGEN

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVES

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.

70-54-53

Fokker F.28

Betreft : Tail section-reinforcement of speedbrake accumulator
Subject brackets.

Van toepassing op : F.28 Aircraft Serial Numbers 11003
Applies to to 11016 inclusive.

Tijdstip van uitvoering : Required before July 15, 1970 unless
Compliance already accomplished.

Datum van inwerkingtreding : June 9, 1970.
Effective date

Uitvoering : In accordance with Fokker Service
Accomplishment Bulletin F.28/53-4 dated 19 May,
1970.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Department of Civil Aviation
Aeronautical Inspection Division
P.O. Box 7555
Schiphol - East
Netherlands.