

**M.A.L.**

(MEDEDELINGEN  
AAN NEDERLANDSE  
LUCHTVARENDEN  
EN EIGENAREN VAN  
LUCHTVAARTUIGEN)

**NEDERLAND**

RIJKSLUCHTVAARTDIENST

LUCHTVAARTINLICHTINGDIENST

112/71

25 okt

(AIR 590)

PLESMANWEG 1—6 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)  
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.*

70-61-76 issue 4

Fokker F.28

Betreft : Engine Controls. Fluid fire shut-off valves - inspection for  
Subject : condition and correct function.

Van toepassing op : F.28 Aircraft Serial Numbers :  
Applies to : 11003 to 11041 inclusive  
11991 to 11994 inclusive, until  
modified in accordance with Service Bulletin  
F.28/28-13 and F.28/76-7.

Tijdstip van uitvoering : As indicated in the Fokker F.28 Alert Servi-  
Compliance : ce Bulletin mentioned below.

Datum van inwerkingtreding : 25 oktober 1971.  
Effective Date :

Uitvoering : In accordance with Alert Service Bulletin F.28/76-  
Accomplishment : A3 dated June 4, 1970, or later R.L.D. approved  
revision.