

**M.A.L.**

(MEDEDELINGEN  
AAN NEDERLANDSE  
LUCHTVARENDEN  
EN EIGENAREN VAN  
LUCHTVAARTUIGEN)

**NEDERLAND**

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGDIENST

135/71

8 dec

(AIR 608)

PLESMANWEG 1—6 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING**

(BLA)

**NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.*

71-55-32 Issue 2

Fokker F.28

- Betreft** : Main gear actuator - inspection of  
**Subject** : bearing and temporary modification to attachment of actuator.
- Van toepassing op** : F.28 Aircraft Serial Numbers:  
**Applies to** : 11003 to 11037 inclusive and 11040, 11991 to 11994 inclusive.
- Tijdstip van uitvoering** : Inspection required not later than July  
**Compliance** : 15, 1971 (See original issue of this Airworthiness Directive) and subsequently every check 1 until Part II of Service Bulletin F.28/32-72 has been carried out or an equivalent R.L.D. approved modification.
- Datum van inwerkingtreding** : December 8, 1971.  
**Effective date**
- Uitvoering** : In accordance with Fokker Service  
**Accomplishment** : Bulletin F.28/32-72 dated July 8, 1971 incl. revision 2, dated 22 November, 1971 or later R.L.D. approved revision.