

M.A.L.

(MEDEDELINGEN
AAN NEDERLANDSE
LUCHTVARENDEN
EN EIGENAREN VAN
LUCHTVAARTUIGEN)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

95/71

2 sep

(AIR 575)

PLESMANWEG 1—6 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.

71-62-27

Fokker F.28

Betreft : Aileron tab drive mechanisme - intro
Subject : of steel extension rod.

Van toepassing op : F.28 Aircraft Serial Numbers:
Applies to : 11003 to 11037 inclusive.
: 11991 to 11994 inclusive.

Tijdstip van uitvoering : Before 15th September, 1971.
Compliance

Datum van inwerkingtreding : 2nd September, 1971.
Effective Date

Uitvoering : In accordance with Fokker Service
Accomplishment : Bulletin F.28/27-55 dated 20 August,
: 1971 or later R.L.D. approved revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Department of Civil Aviation
Aeronautical Inspection Division
P.O. Box 7555
Schiphol Airport - East
The Netherlands.