

M . A . L .

(Mededelingen  
aan nederlandse  
luchtvaardigen  
en eigenaren van  
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGDIENST

32/72

7 apr

(AIR 644)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)  
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.*

**72-18-55  
Fokker F.28**

**Betreft** : Horizontal stabilizer - introduction  
**Subject** : of connection angles in box at rib sta.  
3800-

**Van toepassing op** : F.28 Aircraft Serial Numbers.  
**Applies to** : 11003 to 11025 inclusive 11991,  
11992, 11994.

**Tijdstip van uitvoering** : Required, before 1st April, 1973.  
**Compliance**

**Datum van inwerkingtreding** : April 7, 1972.  
**Effective date**

**Uitvoering** : In accordance with Fokker Service  
**Accomplishment** : Bulletin F.28/55-8, dated 13 March,  
1972, or later R.L.D. approved  
revision.

*All operators of above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

Note Address inquiries regarding this Airworthiness Directive to:  
Department of Civil Aviation  
Aeronautical Inspection Division  
P.O. Box 7555  
Schiphol Airport - East  
The Netherlands.