

M . A . L .

(Mededelingen  
aan nederlandse  
luchtvaardigen  
en eigenaren van  
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGENDIENST

48/72

8 jul

(AIR 655)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)**

**NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de Directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.*

**72-33-25**

**Fokker F.28**

- Betreft** : Pilot seat installation - inspection and  
**Subject** : modification of back rest adjustment mechanism.
- Van toepassing op** : F.28 Aircraft Serial Numbers:  
**Applies to** : 11003 to 11052 inclusive and  
11991 to 11994 inclusive as far as  
equipped with pilot and copilot seats  
of following part numbers: E173213,  
E173214, E171755 and E171756.
- Tijdstip van uitvoering** : Required before July 1st, 1972.  
**Compliance**
- Datum van inwerkingtreding** : July 8, 1972.  
**Effective date**
- Uitvoering** : In accordance with Service Bulletin  
**Accomplishment** : F.28/ ~~Accomplishment~~ 25-38 dated  
June 16, 1972 or later R.L.D.  
approved revision.

*All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

Note: Address inquiries regarding this Airworthiness Directive to:  
Department of Civil Aviation  
Aeronautical Inspection Division  
P.O.Box 7555  
Schiphol Airport - East  
The Netherlands.