

M. A. L.

(Mededelingen
aan nederlandse
luchtvaardigen
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

60/72

25 aug

(AIR 666)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/19) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.

72-39-27

Fokker F.28

Betreft :
Subject : Flap assymetry protection system -
intro of improved routing and
protection of cable loom.

Van toepassing op : F.28 Aircraft Serial number: 11003 to
Applies to 11022 inclusive
11991 to 11992 inclusive

Tijdstip van uitvoering : Required at next check 2.
Compliance

Datum van inwerkingtreding : August 25, 1972
Effective date

Uitvoering : In accordance with Service Bulletin
Accomplishment F.28/27-68 dated 23 June, 1972, or
later RLD approved revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Department of Civil Aviation,
Aeronautical Inspection Division,
P.O. Box 7555,
Schiphol Airport - East,
The Netherlands.