

M. A. L.

(Mededelingen
aan nederlandse
luchtvaardenden
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

102/73

17 Oct

(AIR 798)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)**

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of Civil Aviation Department prescribes hereby the following Airworthiness Directive.

73-64-11

Fokker F-28

- Betreft** : Third crew member oxygen installation-replacement of placards.
Subject
- Van toepassing op** : F-28 Aircraft Serial Numbers:
Applies to Part I: 11003 to 11052 inclusive, 11054 to 11061 inclusive, 11991 to 11993 inclusive as far as equipped with Robert Shaw Oxygen system.
Part II: 11053 to 11062 inclusive.
- Tijdstip van uitvoering** : Required before 1st November, 1973.
Compliance
- Datum van inwerkingtreding** : October 17, 1973.
Effective Date
- Uitvoering** : In accordance with Fokker Service
Accomplishment Bulletin F-28/11-20 dated 14 August, 1973 or later R.L.D. approved revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O.Box 7555, Telex: 15267, Cable: Civilinspec Schiphol
Schiphol Airport-East
The Netherlands.