

M . A . L .

(Mededelingen
aan nederlandse
luchtvaardigen
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGEDIENST

108/73

15 nov

(AIR 802)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of Civil Aviation Department prescribes hereby the following Airworthiness Directive.

73-67-24

Fokker F-28

Betreft Subject	: A.C. Generator supply cables - rework of back-up ring of cabin to stubwing pressure bungs.
Van toepassing op Applies to	: F-28 aircraft Serial Numbers: 11042 to 11069 inclusive
Tijdstip van uitvoering Compliance	: Required before 1st December 1973.
Datum van inwerkingtreding Effective Date	: 15th November 1973.
Uitvoering Accomplishment	: In accordance with Fokker Service Bulletin F-28/24-17 dated 19 October, 1973, or later R.L.D. approved revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555, Telex. 15267, Cable: Civilinspec Schiphol
Schiphol Airport - East
The Netherlands.