

M . A . L .

(Mededelingen
aan nederlandse
luchtvaardigen
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

34/74

19 Apr

(AIR 829)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)**

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of Civil Aviation Department prescribes hereby the following Airworthiness Directive.

74-18-76

Fokker F.28

Betreft: Power controls - inspection for corrosion
Subject: on HPC and RPM control cables in toilet
and luggage compartment area.

Van toepassing op: F.28 Aircraft Serial Numbers:
Applies to: 11003 to 11073 inclusive, 11075 and
11991 to 11993 inclusive.

Tijdstip van uitvoering: Required before 1st July, 1974.
Compliance:

Datum van inwerkingtreding: April 19, 1974.
Effective date:

Uitvoering: In accordance with Fokker Service Bulletin
Accomplishment: F.28/76-16 dated April 8, 1974, or
later R.L.D. approved revision.

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O.Box 7555, Telex 15267, Cable: Civilinspec Schiphol
Schiphol Airport - East
The Netherlands.