

M . A . L .

(Mededelingen  
aan nederlandse  
luchtvaarders  
en eigenaren van  
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGDIENST

105/74

4 Oct

(AIR 889)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of Civil Aviation Department prescribes hereby the following Airworthiness Directive.*

74-63-52

**FOKKER F.28**

**Betreft:** Cargo doors - introduction of improved lock warning switch operating mechanism.  
**Subject:**

**Van toepassing op:** F.28 Aircraft serial numbers:  
**Applies to:** Part I : 11021 to 11062 inclusive  
11991 to 11993 inclusive  
Part II: 11003 to 11062 inclusive  
11991 to 11993 inclusive

**Tijdstip van uitvoering:** before 1st January 1975.  
**Compliance:**

**Datum van inwerkingtreding:** October 4, 1974.  
**Effective Date:**

**Uitvoering:** In accordance with Fokker Service  
**Accomplishment:** Bulletin F.28/52-49 dated 29 Augustus 1974 or later RLD approved revision.

*All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

Note: Address inquiries regarding this Airworthiness Directive to:  
Civil Aviation Department  
Aeronautical Inspection Directorate  
P.O. Box 7555, Telex: 15267, Cable: Civilinspec Schiphol  
Schiphol Airport - East  
The Netherlands