

Ministerie van Verkeer en Waterstaat

Rijksluchtvaartdienst

Luchtvaartinspectie (publ. Nr. 78/143)

24 OCT

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 3 (publ. nr. A110/77) en BLA nr. 74-70-00 uitg. 3 (MAL nr. 35/76) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 78-96-33

FOKKER F. 28

Betreft: Noodverlichting in de ingang van de cabine van VIP-vliegtuigen.
Subject:

Evacuation lights in the cabin entrance of VIP-aircraft.

Of the under mentioned aircraft the evacuation lights in the cabin entrance have erroneously not been installed due to the different cabin lay-out of aircraft in VIP-configuration.

This is not in compliance with FAR 25.812. To rectify this, Fokker has issued Service Bulletin F-28/33-24.

VAN TOEPASSING OP: Serial numbers: 11028, 11045, 11049, 11073,
APPLIES TO: 11088, 11104, 11124.

Tijdstip van uitvoering: Uiterlijk 1 februari 1979.
Compliance: Not later than the 1 February 1979.

Datum van inwerkingtreding:
Effective Date:

Uitvoering: In accordance with Fokker Service Bulletin
Accomplishment: F. 28/33-24
or later RLD approved revision.

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
1117 ZH SCHIPHOL
The Netherlands
Telex: 15267 rldli nl
Telef: 020 - 51632