

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

directie luchtvaartinspectie
Aeronautical Inspection Directorate



Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

BLA nr. 89 - 99

Date: August 25, 1989

F O K K E R

Type: F.27-050

Seq.: 050

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

FLIGHT CONTROLS - ACCESSORY COMPARTMENT CABLE COVERS - INTRODUCTION OF HOSES

Description:

Service experience with the covers installed in accordance with AD (BLA) 88-84 shows that water, coming out of the tubes of the covers of wing STA.3251 LH and STA.3240 RH, may splash when it falls to the bottom of the accessory compartment. Splashing water can make the cover installation less effective in preventing frozen cable systems. To improve the current protection against water-ingress, this Airworthiness Directive (BLA) calls for the installation of hoses on the control cable pulley covers.

Effectivity:

F.27 Mk.050 aircraft serial numbers:

20103 to 20108 inclusive and 20110 to 20134 inclusive, if in post-Service Bulletin F50-27-010 configuration.

Effective date: September 01, 1989

Compliance: required before January 01, 1990

Accomplishment: In accordance with Fokker Service Bulletin F50-27-024 dated August 18, 1989 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par. 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft are receiving the ref. Service Bulletin directly from the manufacturer.

Note:

Address inquiries regarding this AD to:
Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, The Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503 - 63163
Telefax: ()-31-(0)2503 - 40741