

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

directie luchtvaartinspectie
Aeronautical Inspection Directorate



Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

BLA nr. 89-109

Date : September 25, 1989

F O K K E R

Type: F.28-0100

Seq.: 036

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

DOORS - FORWARD S/E DOOR WATER DRAINS - REPLACEMENT

Description:

Water may enter the forward service/emergency (S/E) door, or the space between the door seals and the doorstep. The drain holes may be blocked, either by the door seals or by dirt, or the drain tube from the door vent flap may be blocked by the doorstep. In either case, the accumulated water can freeze, with the result that it is not possible to open the S/E door.

To prevent above mentioned problems, this Airworthiness Directive (BLA) calls for the adjustment of the length of the drain tube and the repositioning of the drain holes.

Effectivity:

F.28 Mk.0100 aircraft serial numbers:

11244, 11245, 11248 to 11256 inclusive, 11259 and 11268 to 11271 inclusive.

Effective date: September 29, 1989

Compliance: required before December 15, 1989

Accomplishment: In accordance with Fokker Service Bulletin F100-52-009 dated September 14, 1989 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63160
Telefax: ()-31-(0)2503-40741

ISSN 0920 - 1084