

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation



directie luchtvaartinspectie
Aeronautical Inspection Directorate

BLA nr: 90-055

Date : May 18, 1990

F O K K E R

Type: F.27 Mk.050

Seq.: 070

Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

POWER PLANT - FUEL DRAIN TANK VENT SLEEVE - REPLACEMENT

Description:

A case was reported of a Fokker F.27 Mk.050 where, upon shutting down engine No. 2, heavy smoke came from the RH engine cowling. Although no fire warning had been activated, the inside of the cowlings showed signs of fire. Furthermore, the vent sleeve on top of the fuel drain collector tank was found broken. Subsequently, Airworthiness Directive (BLA) 89-139 was issued, requiring an inspection of the affected vent sleeves. The present Airworthiness Directive (BLA) requires the replacement of the vent sleeves with improved units.

Effectivity:

F.27 Mk.050 aircraft serial numbers:
20103 to 20184 inclusive.

Effective date: May 25, 1990

Compliance: required before August 16, 1990

Accomplishment: In accordance with Fokker Service Bulletin F50-71-017 dated May 17, 1990 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.
- This AD (BLA) supersedes BLA 89-139 dated November 06, 1989.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63162
Telefax: ()-31-(0)2503-40741

ISSN 0920 - 1084